



## Trench Repair in Electro Plating Workshop

Client LTQ



### Job Description

DGL was contracted by LTQ to repair their severely damaged concrete trench that drained highly corrosive material from their Electro Plating Shop. The job involved:

- Cleaning away all loose material from the trench using high pressure water
- Repairing the floor and walls of the trench using a high build repair mortar
- Installing a highly chemical resistive coating to reduce the damage caused by the chemical runoff