



Balcombe Creek Bridge Restoration

Client

Vic Roads



Job Description

DGL was contracted by VicRoads to undertake the repair work of a concrete bridge in Mount Martha over the Balcombe Creek. The job involved

- Setup of working platform
- Removal of the defective concrete using mechanical hammers
- Preparation of steel reinforcement
- Installation of polymer modified repair mortar
- Installation of anti carbonisation coating